



ENVIROGRAF®



EXCLUSIVE


DRY LINING BOXES

OUT NOW!

COMPLETE WITH **LIFE-SAVING** GASKETS



LOW PRICES



ARE YOU BREAKING THE LAW? WITHOUT GASKETS YOU ARE!



**PROTECTING PROPERTY
PROTECTING LIVES**



Environmental Seals Ltd, Envirograf House, Barfrestone, Dover, Kent, CT15 7JG, United Kingdom

Phone: +44 (0) 1 304 842 555 – Fax: +44 (0) 1 304 842 666 – Email: sales@envirograf.com – URL: www.envirograf.com




ENVIROGRAF®



Are you spreading fire? – Without gaskets you are!

DRY LINING BOXES WITH INTUMESCENT GASKETS FITTED, MEETING THE 16th EDITION IEE REGULATIONS AND DOCUMENT B OF UK BUILDING REGULATIONS

DRY LINING BOXES




In the event of a fire, the cover plate of a socket, switch, or light fitting will sag and disintegrate, leaving a perfect escape route for a fire to travel up the cavity, into an adjoining room or ceiling. Every day, many electrical contractors, and building and design professionals are oblivious of their legal obligations to ensure that the properties they construct, manage, or refurbish comply with current standards and regulations.




THE ABSENCE OF INTUMESCENT GASKETS BREAKS ALL REGULATIONS

In a recent test at the Building Test Centre, flames penetrated a 70-minute-rated partition in just **seven minutes**, causing a complete shut-down of the remainder of the test. With intumescent gaskets, the same type of partition gave 70 minutes integrity and insulation at Chiltern/TRADA.

METAL BOXES BACK TO BACK



In tests at TRADA in a 225mm block wall, back-to-back metal boxes with switch and socket outlets without gaskets burnt through the wall in five minutes, showing how important gaskets are. Boxes fitted with intumescent gaskets in the same type of wall gave **four hours** integrity and insulation.



DON'T TAKE A CHANCE – YOU ARE LIABLE!



**PROTECTING PROPERTY
PROTECTING LIVES**

